

57 PIECES

PRECISION ELECTRIC SCREWDRIVER SET



User Manual

Before use, please carefully read all safety warnings, instructions, illustrations, and regulations marked in the manual.





Safety Information

Before using this product, please read the following safety instructions and follow all normal safety precautions.


Any operation not in accordance with these instructions may result in damage to this product.



Electrical Safety

- 1, The charging cable of electric screwdriver needs to use original accessories, which will greatly reduce the danger of charging.
- 2, Please do not expose the electric screwdriver to the sun burst or placed it in a humid environment, which will lead to the screwdriver rust and can not be used.
- 3, If you can not avoid using the electric screwdriver in a humid environment, please wear silicone type gloves as a protective measure to reduce the risk of electric shock.
- 4, If the electric screwdriver is operated in an electrostatic environment, please install an electrostatic ring to demagnetize the bit to reduce operating accidents.

How To Use




Opening Method

Press the top button.
Organiser pops up
automatically.

Removing the Tool

Remove the tool by
pinching the head of the
accessory screwdriver.




Storage method

Align the tail with the
slot. Then push the top
into the slot.

Part Description

Contents Include:

56 Pieces screwdriver set + a type C charging cable



- ① 1x Electric screwdriver handle
- ② 1x Metal crowbar
- ③ 1x Magnetizer/Demagnetizer
- ④ 1x Tweezers
- ⑤ 12x 35mm long bits
- ⑥ 40x 28mm short bits
- ⑦ 1x Type-C charging cable

Product Specification

Battery capacity: 500mAh
Battery type: Lithium battery
Voltage: 3.7V-DC
Idling speed: 150±10rpm
Electric torque: 0.1-0.3N.m
Manual torque: 3N.m
Charging time: >120mins
Bits specification: H4x28mm & H4x35mm
Bits material: S2 Premium steel







Gear torque comparison table

Gear	Torque value
0	OFF
1	0.1 N.m~0.15 N.m
2	0.15 N.m~0.25 N.m
3	0.25N.m~0.3 N.m













(The above parameters are for the fully charged state.)

Screwdriver Bits Specification:


H4*35mm x 12PCS

 PH0, PH1	 T8H, T10H, T15H, T20H
 SL2.0	 H1.5, H2.0, H2.5
 U2.6	 2.5


H4*28mm x 40PCS

 PH0000, PH000, PH00, PH2	
 SL1.0, SL1.5, SL2.5, SL3.0, SL3.5, SL4.0	
 H0.7, H0.8, H0.9, H1.0, H1.3, H3.0	
 Y0.6, Y1.0, Y2.0, Y2.5, Y3.0, Y1	
 P2, P5, P6	 U2.0, U3.0
 2.0, 2.3	 SQ0, SQ1
 T5H, T6H, T7H, T9H	 T2, T3, T4
 SIM	 W1.5

Electric Screwdriver Description





Using Steps





1. Install bit.




2. Press “”, each press will adjust to a different gear torque.



2. Press “”, tighten the screw and turn on the light at the same time.



3. Press “”, loosen the screws and turn on the light at the same time.

Note:

If the main unit does not work after 10 seconds, the LED light will go out automatically.

OLED Screen Instructions

The product is equipped with three torque, can be switched to different gears through the "gear adjustment" button.

"0 gear" for the shutdown gear, this gear motor and lighting are not working; switch to 1-3 gear to start working, the screen into the work interface.

Press the direction button, the screwdriver head rotates while the LED lights up, the screen will synchronously display the number of gears, and the small plane icon will fly cyclically according to the direction of the button.



The screen icon shows "🚀" for twisting the screws tightly, the screen icon shows "👉" for twisting the screws loosely.

Charging Instruction

Charging using the Type-C universal charging port, the product's charging screen displays a cyclic incremental flashing of the battery indicator icon. When fully charged, the battery icon remains lit.

1, Please charge fully when using the screwdriver in first time and the charging time is no more than 2.5 hours.

2, Please charge the once a month to maintain a good performance.

Note:

When the battery icon shows empty battery. Please use the Type-C charging cable to charge it promptly.

